

DIGI Quick Installation

GCC cutting plotters • installation without CD

Before you begin


The user manual and additional installation guides are available at refo.cz/stahnout. Password for opening the user manual PDF: refoprirucka.

STEP 1 DOWNLOAD THE INSTALLATION FILES

Download the driver and software from the official GCC Download Area.

Download link

www.gccworld.com/download.php → select Cutting Plotter.



1 Select your plotter model

In the Cutting Plotter section, click the model you use. If you are unsure, check the model name on the machine label.

[Company](#)
[Applications](#)
[Products](#)
[Technology](#)
[Support](#)
[Contact](#)
[Link](#)

[Tech Support](#)
[Download Area](#)
[Product Termination Policy](#)

Vinyl Cutter

Vinyl Cutter ▾



Expert II A



i-Craft™ 2.0



AR-24



Expert II



Puma IV



Jaguar V / Jaguar V (PPF)



RX II / RX II (Creasing)

Then expand the required section

For installation, you will need Driver and Software. Always choose files that match your plotter model and operating system.

1.1 Driver

Download the latest driver for your plotter model and connection type. The current driver version is shown next to the file on the GCC website.

Direct access to drivers

[GCC Download Area](#) → Cutting Plotter → your model → Driver

Software

Product Brochure

Driver

User Manual

Other

1.2 Software

For GCC Expert II, Puma 4, Jaguar 5 and RX II plotters, download GreatCut-S for Windows or macOS.

Software

Title	Size	Download
GreatCut-S (265022950G) 5.005 (2022-400) FOR Mac	148 MB	Download
GreatCut-S (265022950G) 5.005 (2022-400) FOR Windows	68.0 MB	Download
Sure Cuts A Lot Pro 5 _Win64bit	521 MB	Download
Sure Cuts A Lot Pro 5 _Win32bit	34.0 MB	Download
Sure Cuts A Lot Pro 5_Mac	39.9 MB	Download
SignPal V19	818 MB	Download
GreatCut 4 for Windows (v17.0.26.25853)	303 MB	Download

2.1 Install the driver

1. Turn on the cutting plotter and connect it to the computer by USB.
2. Wait until the system detects the device. Do not disconnect USB during installation.
3. Open the downloaded driver and complete the installation as instructed.
4. In Windows, check the plotter under Devices and Printers.

2.2 Install GreatCut-S

Activation instructions are provided in GreatCut-S Software Installation and Activation Guide, available in the REFO download section.

Activation guide

refo.cz/stahnout → Installation guides → GreatCut-S Software Installation and Activation Guide

2.3 Replace an old GreatCut 4 voucher

If your plotter came with an old GreatCut 4 voucher, exchange it in GCC Club for a new GreatCut-S serial number. If you already have a GreatCut-S voucher, proceed directly to activation.



Identify the voucher

Check the product name on the voucher. An old GreatCut 4 code must be converted; a GreatCut-S code can be activated directly.

3.1 Sign in to GCC Club

Open GCC Club and sign in. In the left menu, choose Upgrade GreatCut and enter the required information from the old voucher.

GCC Club

gccf.gcc.com.tw/gccclub/login.aspx


3.2 Obtain the new serial number

After a successful exchange, the new GreatCut-S serial number will be displayed. Save it; you will need it to activate the software.

530013-041734-180827-180827-180827

4 Activate GreatCut-S

Use the new serial number to complete activation according to the GreatCut-S Software Installation and Activation Guide. You can start using the software after activation.



Technical support for the Czech Republic and Slovakia

REFO, spol. s r.o.
Lipenska 8, 370 01 Ceske Budejovice, Czech Republic
phone: +420 387 222 806 • email: tomek@refo.cz

Useful links

[REFO downloads](#) • [GCC drivers and software](#)